-) CONNECT SENSING LINE TO A STRAIGHT SECTION OF PIPING, MINIMUM 10 PIPE DIAMETERS OR 24", WHICHEVER IS
- PROVIDE 1/2" VALVE IN BOTTOM OF CONDENSATE LINE.
- 3/4" BYPASS FOR INITIAL WARM-UP.
- FIRST SHUTOFF VALVE INSIDE BUILDING
- ON STEAM SERVICES, PROTECT THE PRESSURE GAUGE WITH A PIGTAIL SIPHON.
- FIRST SHUTOFF VALVE AND TRAP SHOULD BE WITHIN 10 FEET OF THE EXTERIOR WALL ENTRY POINT.

ML-2, ADDITIONAL REQUIREMENTS (REMOVE THIS NOTE WHEN IN-AND QA REVIEWS ARE REQUIRED. ML-4 PROJECTS. FOR ML-1/ DRAWING DEVELOPED FOR ML-3/

	3 1-4	I
ADTS ADTS ADTS ADTS	ī	
	1-4-06	
RINDER STEAM	c	
G S: E	막	
ADTS	ADDED KEYED NOTE 7 AND REVISED	
DESIGN OR DATE	끃	İ
OF RUCH R XED ON R R SI	Ą	I
1	Ą	Ī
HKO SUB FROST ROST ROST 4	8	Ι
<u>→</u>	ᅙ	

ST-D3020-2